

BULLETIN

MISC.

(11/09)

This bulletin is to make you aware of issues that have been identified by the OD Team or other retailers and suggest Tenant's architect and engineer pursue further as it relates to Tenant's contract documents.

- The Food Court is not on the mall's central plant. All food court tenants shall design for and install roof top units to accommodate HVAC needs.
- The Food Court is slab on grade despite being on the second level.
- There is no common grease trap for the food court tenants. Tenants are required to install individual grease systems in accordance with local code.
- There are random areas in the Macy's wing on the upper level where the floor elevation changes within the space. Field verify floor elevations and conditions.