

# **BULLETIN**

## **MISC.**

**(05/09)**

**This bulletin is to make you aware of issues that have been identified by the OD team or other retailers and suggest Tenant's architect and engineer pursue further as it relates to Tenant's contract documents.**

- Tenant storefronts must extend to the bottom of the landlord's bulkhead. In various locations, there are existing mall common area HVAC diffusers. Tenant must incorporate these diffusers into their storefront design. Refer to design manual for additional information.