

BULLETIN

MISC.

(05/09)

This bulletin is to make you aware of issues that have been identified by the OD Team or other retailers and suggest Tenant's architect and engineer pursue further as it relates to Tenant's contract documents.

- Food Court tenants are required to install individual grease traps to be maintained by tenant.
- Part of the Mall is 120/208v and the other is 277/480v. Refer to manual for drawing showing split.