

# BULLETIN

## MISC.

(05/09)

**This bulletin is to make you aware of issues that have been identified by the OD team or other retailers and suggest Tenant's architect and engineer pursue further as it relates to Tenant's contract documents.**

- Tenant must extend storefront height up to the Landlord bulkhead.
- Part of the Mall is 120/208v and the other is 277/480v. Refer to the Tenant Design Manual for drawing showing split.
- Tenants are required to replace existing pneumatic HVAC controls with new digital controls.