

BULLETIN

MISC.

(10/09)

This bulletin is to make you aware of issues that have been identified by the OD team or other retailers and suggest Tenant's architect and engineer pursue further as it relates to Tenant's contract documents.

- The mall has multiple roofing contractors for different areas of the mall roof. Contact the mall OD for details and contact information. The specified roofer is a required contractor and no substitutions will be allowed.